



Certificate No.: SIN25.505559.J0

CERTIFICATE OF INSPECTION

Importer: SAYED KAMAL ABDUL AL ABDULAZIZ Address: AHMED BADAWY ST ABUELNOMROS - GIZA - EGYPT			Exporter: SHENZHEN GROUP TIGER TECHNOLOGY CO., LTD Address: RM642, BLOCK A, WANHE SCI-TECH PLAZA, NO 7 HUITONG RD, PHOENIX STREET, GUANGMING DISTRICT, SHENZHEN, GUANGDONG, CHINA		
Place of Inspection: CHINA			Port of discharge (in Egypt): SOKHNA , Port-EG		
Producer: SHENZHEN GROUP TIGER TECHNOLOGY CO., LTD Address: RM642, BLOCK A, WANHE SCI-TECH PLAZA, NO 7 HUITONG RD, PHOENIX STREET, GUANGMING DISTRICT, SHENZHEN, GUANGDONG, CHINA			Invoice Number: SYK-6352	Invoice Date: 01/11/2025	Invoice Value: 2,640.00 USD
Item	Quantity/Uni	Product Description	BRAND	Accredited Standards	Country of Origin
1	70CTNS	PLASTIC KITCHEN WARE	GROUP TIGER	ES880/2008	CHINA
2	50CTNS	ELECTRIC HAND BLENDER	GROUP TIGER	ES1781/2025 ES1590/2010	CHINA
3	75CTNS	GLASS WARE	GROUP TIGER	ES1869/2018(2022)	CHINA
4	80CTNS	METAL KITCHEN WARE	GROUP TIGER	ES494-2/2022 EC1935/2004	CHINA
5	20CTNS	WOODEN KITCHEN WARE	GROUP TIGER	ES7424-1/2011	CHINA
6	20CTNS	PORCELAIN KITCHEN WARE	GROUP TIGER	ES923/2019	CHINA

Remarks	ACID No.: 4477159332025110011
Authorized Office : IAQC SINGAPORE Signature : T.A.MOHSE Date of Inspection: 08 /11/2025 --- Issuance Date: 10 /11 / 2025	
This certificate is issued for the General Organization for Export and Import Control (GOEIC) (according to the requirements of the Product Inspection program in Egypt. This Certificate is also subject to the applicable IAQC Conditions of contracting available at: http://www.iaqc-singapore.com . This document does not discharge exporters from their contractual obligations in relation to quality and quantity of the goods referred to herein, nor does it discharge the exporter or the importer from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on IAQC. This document does not evidence shipment. GOEIC may reject the consignment covered by this COI if found to be Non-Conforming on verification at the Egyptian border points.	