



Certificate No.: SIN25.505130.J0

CERTIFICATE OF INSPECTION

Importer: HOME TECH FOR IMPORT AND EXPORT AND TRADING AGENCIES Address: ZAIN ELDIN ALABDEEN ST . ELMASRY AREA . ELMARG CAIRO , EGYPT			Exporter: YIWU DOGO IMPORT AND EXPORT CO.,LTD Address: ROOM NO 2106, WUYUE NO.1 BUILDING, JIANGDONG STREET, YIWU CITY,ZHEJIANG PROVINCE, CHINA		
Place of Inspection: CHINA			Port of discharge (in Egypt): SOKHNA , Port-EG		
Producer: YIWU DOGO IMPORT AND EXPORT CO.,LTD Address: ROOM NO 2106, WUYUE NO.1 BUILDING, JIANGDONG STREET, YIWU CITY,ZHEJIANG PROVINCE, CHINA			Invoice Number: FN2508080	Invoice Date: 08/08/2025	Invoice Value: 11,458.76 USD

Item	Quantity/Uni	Product Description	BRAND	Accredited Standards	Country of Origin
1	100CTNS	GLASS WARE	MAZOTTE	ES1869/2018(2022)	CHINA
2	20CTNS	METAL KITCHENWARE	MAZOTTE	ES494-2/2022 EC1935/2004	CHINA
3	30CTNS	PLASTIC KITCHENWARE	MAZOTTE	ES880/2008	CHINA
4	70CTNS	DECORATION ITEMS	MAZOTTE	ES7825/2014 IEC60598-1/2014 IEC62717/2014 IEC62722-2-1	CHINA
5	50CTNS	ORGANIZER	MAZOTTE	ES7321/2011	CHINA
6	50CTNS	WOODEN ITEM	MAZOTTE	ES7424-1/2011	CHINA
7	25CTNS	BLOWER	MAZOTTE	ES1781/2020	CHINA

Remarks	ACID No.: 7689361792025080018
Authorized Office : IAQC SINGAPORE Signature : T.A.MOHSEN	
Date of Inspection: 08/08/2025 --- Issuance Date: 10 / 08 / 2025	
This certificate is issued for the General Organization for Export and Import Control (GOEIC) (according to the requirements of the Product Inspection program in Egypt. This Certificate is also subject to the applicable IAQC Conditions of contracting available at: http://www.iaqc-singapore.com . This document does not discharge exporters from their contractual obligations in relation to quality and quantity of the goods referred to herein, nor does it discharge the exporter or the importer from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on IAQC. This document does not evidence shipment. GOEIC may reject the consignment covered by this COI if found to be Non-Conforming on verification at the Egyptian border points.	