



Certificate No.: SIN26.000037.J0

CERTIFICATE OF INSPECTION

Importer: IMAGE FOR IMPORT AND EXPORT AND TRADING AGENCIES (HODA ELSAYED AHMED AHMED ALDAMATTY) Address: GROUP 5 BUILDING 996 . 6TH OF OCTOBER . GIZA . EGYPT	Exporter: YIWU DOGO IMPORT AND EXPORT CO.,LTD Address: ROOM NO 2106, WUYUE NO.1 BUILDING, JIANGDONG STREET, YIWU CITY,ZHEJIANG PROVINCE, CHINA		
Place of Inspection: CHINA	Port of discharge (in Egypt): SOKHNA , Port-EG		
Producer: YIWU DOGO IMPORT AND EXPORT CO.,LTD Address: ROOM NO 2106, WUYUE NO.1 BUILDING, JIANGDONG STREET, YIWU CITY,ZHEJIANG PROVINCE, CHINA	Invoice Number: EMG-9640	Invoice Date: 01/12/2025	Invoice Value: 13,994.00 USD

Item	Quantity/Uni	Product Description	BRAND	Accredited Standards	Country of Origin
1	206CTNS	METAL KITCHEN WARE	MAZOTTE	ES494-2/2022 EC1935/2004	CHINA
2	14CTNS	BEATER USB	MAZOTTE	ES1781/2025 ES1590/2010	CHINA
3	210CTNS	GLASS WARE	MAZOTTE	ES1869/2018(2022)	CHINA
4	322CTNS	PORCELAIN KITCHEN WARE	MAZOTTE	ES923/2019	CHINA
5	39CTNS	PLASTIC KITCHEN WARE	MAZOTTE	ES880/2008	CHINA
6	7CTNS	ELECTRIC TEA POT	MAZOTTE	ES1781/2025 ES5813/2007	CHINA
7	5CTNS	MAT	MAZOTTE	ES791-1/2018	CHINA

Remarks	ACID No.: 4744856762025120012
Authorized Office : IAQC SINGAPORE Signature : T.A.MOHSEN	
Date of Inspection: 23/12/2025 --- Issuance Date: 25 / 12 / 2025	
This certificate is issued for the General Organization for Export and Import Control (GOEIC) (according to the requirements of the Product Inspection program in Egypt. This Certificate is also subject to the applicable IAQC Conditions of contracting available at: http://www.iaqc-singapore.com . This document does not discharge exporters from their contractual obligations in relation to quality and quantity of the goods referred to herein, nor does it discharge the exporter or the importer from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on IAQC. This document does not evidence shipment. GOEIC may reject the consignment covered by this COI if found to be Non-Conforming on verification at the Egyptian border points.	